



# Survey Report

(007)

|   |                                  |  |                               |                                     |                                 |
|---|----------------------------------|--|-------------------------------|-------------------------------------|---------------------------------|
| <b>GPS</b> (Coordinate of Quarry Site)          | N: 34 32 58.4<br>E: 069 45 09.8  |  |                               |                                     |                                 |
| GPS coordinates from access road to Quarry Site | ~                                |  |                               |                                     |                                 |
| <b>Sample</b>                                   | Granite <input type="checkbox"/> | Marble <input checked="" type="checkbox"/> | Onyx <input type="checkbox"/> | Travertine <input type="checkbox"/> | Others <input type="checkbox"/> |

**Pictures (Road, General Site, Quarry Site and Surveyor Photo):**



**Site Report:**

|                          |                                       |
|--------------------------|---------------------------------------|
| Province:                | Kabul                                 |
| District:                | Serobi                                |
| Village:                 | Kotagai "1"                           |
| Site Distance form Road: | Adjacent to 4Km unsealed road         |
| Road Type and Condition  | Unsealed road and good condition      |
| Water Sources            | Not available                         |
| Power Sources            | Electricity facility is not available |
| Status of Quarry Site    | Active                                |
| No's of Families:        | 5                                     |
| No's of Men:             | 10                                    |
| Community Leader Name:   | Malak Baseer                          |
| Telephone No:            | ~                                     |

