



Survey Report

(038)

| | | | | | |
|--|-------------------------------------|---|----------------------------------|--|------------------------------------|
| GPS (Coordinate of Quarry Site) | N: 34 24 35.1 E: 069 11 30.7 | | | | |
| GPS coordinates from access road to Quarry Site | N: 34 24 49.8 E: 069 11 29.4 | | | | |
| Sample | Granite <input type="checkbox"/> | Marble <input checked="" type="checkbox"/> | Onyx <input type="checkbox"/> | Travertine <input type="checkbox"/> | Others <input type="checkbox"/> |

Pictures (Road, General Site, Quarry Site and Surveyor Photo):



Site Report:

| | |
|--------------------------|---|
| Province: | Kabul |
| District: | Charsiab |
| Village: | Khair Abad "2" |
| Site Distance form Road: | Access unsealed road to mine |
| Road Type and Condition | Unsealed Road |
| Water Sources | Water available because Logar river near with this site |
| Power Sources | Electricity facility is available |
| Status of Quarry Site | Active |
| No's of Families: | 2000 |
| No's of Men: | 6000 |
| Community Leader Name: | Alhaj Naib Khan |
| Telephone No: | ~ |



USAID
FROM THE AMERICAN PEOPLE

GPS Survey Reports,
 Eng. Shahmard Yawar, AMS International Consulting,
www.AfghanMarbleStone.com