



# Survey Report

(008)

<b>GPS</b> (Coordinate of Quarry Site)	N: 34 34 00.7 E: 069 44 46.4				
GPS coordinates from access road to Quarry Site	~				
<b>Sample</b>	Granite <input type="checkbox"/>	Marble <input checked="" type="checkbox"/>	Onyx <input type="checkbox"/>	Travertine <input type="checkbox"/>	Others <input type="checkbox"/>

**Pictures (Road, General Site, Quarry Site and Surveyor Photo):**



**Site Report:**

Province:	Kabul
District:	Serobi
Village:	Manu
Site Distance form Road:	Adjacent to 18Km unsealed road
Road Type and Condition	Unsealed road and good condition
Water Sources	Not available
Power Sources	Electricity facility is not available
Status of Quarry Site	Inactive
No's of Families:	~
No's of Men:	~
Community Leader Name:	Malak Akhtar
Telephone No:	~

