



Survey Report

(018)

GPS (Coordinate of Quarry Site)	N: 34 43 16.7 E: 070 11 50.4				
GPS coordinates from access road to Quarry Site	N: 34 42 01.1 E: 070 12 25.6				
Sample	Granite <input type="checkbox"/>	Marble <input type="checkbox"/>	Onyx <input type="checkbox"/>	Travertine <input type="checkbox"/>	Others <input type="checkbox"/>

Pictures (Road, General Site, Quarry Site and Surveyor Photo):



Site Report:

Province:	Laghman
District:	Armal Khwar
Village:	Sahak "2"
Site Distance from Road:	17Km unsealed road from asphalt road
Road Type and Condition	Unsealed and good condition
Water Sources	Water not available
Power Sources	Electricity facility is not available
Status of Quarry Site	Inactive
No's of Families:	~
No's of Men:	~
Community Leader Name:	Ghulam Mohammad
Telephone No:	~

