



Survey Report

(032)

| | | | | | |
|---|---------------------------------------|---------------------------------|-------------------------------|--|---------------------------------|
| GPS (Coordinate of Quarry Site) | N: 34 45 09.0 E: 068 23 07.4 | | | | |
| GPS coordinates from access road to Quarry Site | Adjacent to unsealed road | | | | |
| Sample | Granite <input type="checkbox"/> | Marble <input type="checkbox"/> | Onyx <input type="checkbox"/> | Travertine <input checked="" type="checkbox"/> | Others <input type="checkbox"/> |
| Pictures (Road, General Site, Quarry Site and Surveyor Photo): | | | | | |
| | | | | | |
| Site Report: | | | | | |
| Province: | Parwan | | | | |
| District: | Surkh parsā | | | | |
| Village: | Dara-e-Turkman dastzo Awpro | | | | |
| Site Distance form Road: | Adjacent to unsealed road | | | | |
| Road Type and Condition | Unsealed | | | | |
| Water Sources | Water available | | | | |
| Power Sources | Electricity facility is not available | | | | |
| Status of Quarry Site | Inactive | | | | |
| No's of Families: | 18 | | | | |
| No's of Men: | 42 | | | | |
| Community Leader Name: | ~ | | | | |
| Telephone No: | ~ | | | | |

