



Survey Report


(063)

GPS (Coordinate of Quarry Site)	N: 34 50 54.1 E: 067 38 47.5
--	---------------------------------

GPS coordinates from access road to Quarry Site	Adjacent to unsealed road
--	---------------------------

Sample	Granite	Marble	Onyx	Travertine	Others
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Pictures (Road, General Site, Quarry Site and Surveyor Photo):



Site Report:

Province:	Bamyan
District:	Shaheedan
Village:	Dara-e-Khushak
Site Distance form Road:	Adjacent to unsealed road
Road Type and Condition	Unsealed and bad condition
Water Sources	Water available 1km
Power Sources	Electricity facility is not available
Status of Quarry Site	Active
No's of Families:	~
No's of Men:	~
Community Leader Name:	~
Telephone No:	~

